

Coatings Conditions Survey Federal Center

CCC&L



Corrosion Control

Client/Owner: General Services Administration

Project Location: Chicago, IL

CCC&L performed coatings condition surveys on the buildings comprising the Federal Center – Everett M. Dirksen, John C. Kluczynski, and the US Post Office Loop Station.

- Performed on-site and laboratory evaluations of painting materials and methods on exterior building surfaces.
- Identified salient coating appearance attributes including instrumental color analyses and numerical conversion to Munsell.
- Determined original paint application and surface preparation methodologies.
- Conducted a coating condition assessment to determine suitability for overcoating.
- Performed laboratory analyses including quantitative lead in paint, FTIR paint type identification and chromochronology.